

# Venus OS v2.30

Bits & pieces of documentation that needs to go into the normal documentation once v2.30 goes live.

## Network watchdog

- use a minimum delay of 5 minutes when there was no contact with VRM yet to prevent a reboot loop

to be further explained.

## Error 47

data partition error; to be further explained.

## VRM Portal errors

tbd.

Once live; this needs to be added here:

[https://www.victronenergy.com/live/vrm\\_portal:troubleshooting\\_ccgx\\_vrm\\_connectivity](https://www.victronenergy.com/live/vrm_portal:troubleshooting_ccgx_vrm_connectivity)

From:

<https://www.victronenergy.com/live/> - **Victron Energy**

Permanent link:

<https://www.victronenergy.com/live/venus-os-2.30?rev=1553158699>

Last update: **2019-03-21 09:58**

